


Thank you for purchasing the Digital S-Line Indicator.  
For proper operation, please read this manual thoroughly before use.

### PARTS IDENTIFICATION


#### Display Rotates 270°

Easy to read from any position.



### BATTERY REPLACEMENT

- 1 Remove the (2x) battery screws using (+) PH#0 screwdriver. Place a small standard screwdriver in the notch to gently pry open the cover and slide out the battery.
- 2 Insert the new battery following the polarity markings on the cover.
- 3 Replace Battery Cover and tighten screws to secure.



**NOTICE** Use only CR2032 type battery.


### POWER

#### 【Power ON】

Press [MODE], [SET], or Center Button to turn on power.

#### 【Power OFF, Sleep Mode】

Press and Hold the [SET] button to enter Sleep Mode; continue pressing to turn power OFF.



- ※ Sleep Mode is entered automatically if gauge is idles for about 20 min.
- ※ To exit Sleep Mode, press any button or move the Spindle.
- ※ When remaining battery level is low, the 『B』 icon is displayed; please replace battery.
- ※ Press and hold [SET] and [MODE] at same time for about 4 sec. to display "CLEAR" and reset all settings (except units, and resolution).

### FEATURES

- Tolerance Setting capability
- Calculation capability
- Display rotates 270°
- Programmable "Favorite" Button  
(Can be set for one touch access to frequently used functions.)
- MIN, MAX, MINMAX (DELTA, or TIR) display functions
- Direction of measurement (+ / -) switchable
- Preset function
- Sleep mode (after approx. 20 min.)
- Made in Switzerland

### SPECIFICATIONS

Model No.	DEI-WKS1	DEI-WKS2
Measurement Range	0-12.5mm	
Resolution	0.01mm	0.001mm
Displayed Resolution	0.01mm	0.01mm/0.001mm (switchable)
Accuracy	0.02mm	0.003mm
Measurement Force	Less than 1.5N	
Repeatability	0.002mm	
Mounting Shaft Diameter	φ 8mm	
Operating Temp. Range	5~40°C	
Power Supply	CR2032 (Lithium cell) × 1	
Weight	115g	

### TROUBLESHOOTING

Error Condition	Corrective Action
Measured value is wrong	<ul style="list-style-type: none"> <li>● Clean measuring surfaces with lens tissue or similar.</li> <li>● Confirm and re-set 0-Point setting.</li> </ul>
<ul style="list-style-type: none"> <li>● LCD does not display</li> <li>● Displayed value is unstable</li> <li>● Display is hard to read</li> </ul>	<ul style="list-style-type: none"> <li>● Cycle power by removing and replacing battery.</li> <li>● Replace battery with new one.</li> </ul>

※ If problem persists, or if you have any questions, please contact distributor or place of purchase.


※ Please note, manufacturer is unable to respond to inquires or provide service directly. Please contact distributor or place of purchase.

### HOW TO USE

- ① Mount indicator securely, such as on optional Magnetic Base, and make sure that the Spindle is perpendicular to the measurement surface.
- ② Press [MODE], [SET], or Center Button to turn on power.
- ③ Check that the probe is in contact with surface, and refer to the following to set the 0-Point.
  - Refer to** Function Setup: "Preset Value"
  - Refer to** Programmable "Favorite" Button: "Zero Set"
  - LCD will display "0.00mm"
- ④ With Gauge body held fixed, and the probe in contact with the workpiece, the LCD will display the difference between workpiece and reference plane.


**See Reverse for "FUNCTION SETUP"→**

## FUNCTION SETUP



## Programmable "Favorite" Button

- Center Button can be programmed to call up a frequently used function with a single press while taking measurements.
- ※ Programmed setting is reset when power is turned off.




**CAUTION**

- This is a precision instrument, handle with care. Do not drop or subject to excessive forces.
- Keep away from high voltage and strong magnetic fields; instrument damage may result.
- Do not use or store in direct sunlight or locations with high temperatures such as in a car, or near a stove or heat source.
- When taking measurements, hold gauge securely, such as in magnetic base. (sold separately)
- Please do not disassemble or modify.
- Remove dust and cutting chips after use and apply rust preventative oil to metallic surfaces. Please keep out of reach of children.
- Do not use organic solvents to clean the body of the instrument.
- When not being used for a long period of time, please remove battery.
- Only use as directed. Improper use may cause accident or injury.

### 【Measurement Display】

Press the [MODE] Button, or Press-and-hold, to access and cycle through the functions as show in the chart below. When the function is displayed, press Center Button to access.



**SC Niigata seiki Co., Ltd.**

6-15-22, Tsukanome, Sanjo, Niigata, Japan, 955-0055  
Tel.: +81-256-31-5670 Fax.: +81-256-39-7730  
MAIL [intl.sales@niigataseiki.co.jp](mailto:intl.sales@niigataseiki.co.jp)  
URL <http://www.niigataseiki.co.jp>

I300-K  
1604