SK ПидаГа Леки

INSTRUCTION MANUAL

GDCS-25STG


Model

No.

Precision Measuring Tool DIGITAL MINI DEPTH GAUGE

Thank you for purchasing Niigata Seiki Digital Mini Depth Gauge. This product is a digital instrument for measuring depth.

- For safe and proper use of this product, please read this instruction manual before use and follow the procedures described. Keep this manual with the instrument for future reference.
- Keep this manual with the instrument if transferred or leased to a third party.
- For inquiries about this product, please contact dealer or Niigata Seiki at the address listed on the following page.




SAFETY PRECAUTIONS Please Observe

To prevent harm to yourself or others, and to prevent damage to property, always follow the procedures marked by the following symbols.

Denotes a prohibition -You **MUST NOT** do

Denotes a requirement -You **MUST** do



Contamination of surfaces may cause measurement error.

A temperature difference between the object to be measured and the gauge may cause measurement error. Allow time for the temperatures to equilibrate.

INSERTING • REPLACING BATTERY

(1) Slide cover in direction of arrow.


2 Insert battery with (+) side outward.


3 Replace battery cover.

Battery Cover

Notice Use only CR2032 type battery Use care to avoid damaging terminals when inserting battery.

- Terminals may be broken if battery is pressed straight down.
- Insert battery at angle, underneath the small hook, as shown.





TROUBLESHOOTING

Q. Nothing is displayed on LCD.

A. The battery may be running low, please replace battery with a new one.

- Q. With power on, the number on the LCD does not change as Display Unit is moved.
 - A. Please reset by removing battery for about 30sec., and then replacing.
- Q. Nothing happens when buttons are pressed.
- A. Make sure battery is properly inserted.
- Q. The characters "MIN", "MAX", or " \triangle " are displayed on LCD.
- A. Cycle power, or apply several long presses to [HOLD] Button. Use as normal once character is off.
- Q. The correct value is not displayed.
- A. High humidity may cause dampness. Please dry off the instrument and use only in dry location.

SERVICE

- If Instrument is not working properly, or if you have any questions, please contact distributor or place of purchase.
- Please note, manufacturer is unable to respond to inquires or provide service directly. Please contact distributor or place of purchase.

SPECIFICATIONS

| Measurement Range | 0 - 25mm |
|-----------------------------|--|
| Instrument Error Resolution | $\%$ Not including quantization error (± 1 count) |
| • Display | 4 Digit LCD |
| • Auto Off | approx. 20 min. |
| • Max. response speed | Slide to Right1.5m/s Slide to Left0.75m/s |
| | %Left/Right as shown in diagram at top of manual. |
| • Operating Temp. Range | $0^{\circ}C \sim 40^{\circ}C$ |
| • Storage Temp. Range | $-10^{\circ}C \sim 60^{\circ}C$ |
| • Power | (1x) CR2032 Lithium Battery |
| Battery Life | approx. 2.5 years in normal use. |
| • Accessory | CR2032 Lithium Battery (1x, for test |

Accessory CR2032 Lithium Battery (1x, for test)


HOW TO USE

Power ON/OFF

- (1) To turn on, press the [ON/OFF] Button.
- (2) To turn off, press the [ON/OFF] Button.
- ③ With power on, press the [HOLD] Button to fix the value on the display.

Absolute Measurement

- 1) Turn on power, and loosen the Lock Screw.
- (2) Place the Base on a flat surface, and push down the Scale. When the Probe contacts the surface, press the [ZERO] Button. (Fig. 1) The Display will read "0.00mm" and it is ready for measurements.
- (3) When placed on workpiece with Scale lowered into groove, the depth of the groove will be displayed. (Fig. 2)




Comparative Measurement

- 1) Turn on power, and loosen the Lock Screw.
- (2) Place the Base on the Reference Part, and push down on the Scale so that the Probe contacts the bottom of the Groove, then press the [ZERO] Button. (Fig. 3)

The Display will read "0.00mm" and it is ready for measurements.

(3) When placed on workpiece with Probe in the groove, the change in depth relative to the Reference Part will be displayed. (Fig. 4)



AFTER USE CARE • STORAGE

After use, wipe off any dirt or oil from measuring surfaces, sliding surfaces, and exterior using a dry cloth and perform rust prevention treatment.

For rust prevention, lightly apply anti-rust oil, or place in rust preventive bag.

Store with Lock Screw loosened.

If stored with Lock Screw tight, expansion due to temperature changes may cause excessive force which will cause inaccuracy.

- Store in a cool, dry, and dark location in the provided case. Keep out of direct sunlight and moisture, and please keep secure from unauthorized personnel.
- Remove battery if Instrument will not be used for a long period of time.

🕰 Niigata seiki Co., Ltd. 5-3-14. Tsukanome, Sanio, Niigata, Japan, 955-0055

Tel.:+81-256-33-5522 Fax.:+81-256-33-5518 MAIL intl.sales@niigataseiki.co.jp URL http://www.niigataseiki.co.jp