


Thank you for purchasing the Digital Gap Caliper.
Before use, please read this document thoroughly for proper operation.

PARTS IDENTIFICATION



- | | |
|----------------------|---------------------------|
| 1. Probe | 9. [HOLD] Button |
| 2. Reference Surface | 10. Connector (*) |
| 3. Base | 11. Main Beam |
| 4. Probe Holder | 12. Battery Cover |
| 5. Jaw | 13. [ZERO] Button |
| 6. Clamp Screw | 14. Power [ON/OFF] Button |
| 7. LCD Display | 15. Lock Nut |
| 8. Lock Screw | |

(*) Output connector function not available for this model.

USAGE NOTES




- Before use, please wipe off oil protectant using a soft, oiled cloth.
- This is a precision instrument, handle with care. Do not drop or subject to excessive force.
- Do not damage scale or scratch instrument. Do not apply ID numbers with engraver.
- Make sure probe Lock Nut is tight before use.
- Keep away from direct sunlight. Do not store instrument in extreme temperatures.
- Avoid using in locations with high electric fields, such as near fluorescent lights or switching power supplies, as it may cause erroneous reading to display on LCD.
- When instrument will not be used for one month or more, please remove the battery to prevent damage from battery fluid leakage.

OPERATION

<Absolute Measurement>

1. Turn on power.
2. Slide the Probe Holder to the desired position and tighten the Clamp Screw. (Figure:1)
3. Place the Caliper on a flat surface and with probe tip in contact with surface, press the [ZERO] Button. When display reads "0.00mm", gauge is ready for use.
4. Place gauge on workpiece, with probe tip on location to measure and take measurement.

※ **Probe Holder must be secure with Clamp Screw tight (Step 2. above) to prevent measurement error. (Figure:2)**



<Relative Measurement>

Press the [ZERO] Button with probe tip on reference surface and subsequent measurement will show difference between reference and measured surface.



※ Display reading can be held by pressing the [HOLD] Button.

PLEASE NOTE

Base must be flat on surface for correct measurement. (Figure:3)

EXAMPLE

Loosen the Lock Screw and slide the Probe up and down to take measurement.




BATTERY REPLACEMENT

1. Slide Battery Cover in direction of arrow.
2. Insert battery with (+) side outward.
3. Replace Battery Cover.

Notice

Only use SR44 type battery.



TROUBLESHOOTING

- Q. Nothing is displayed on LCD, or the numbers are flashing.
A. Is the battery running low?
- Q. With power on, the number on the LCD does not change as the slide is moved.
A. Please reset by removing battery for about 30sec., and then replacing.
- Q. Nothing happens when buttons are pressed.
A. Is the battery inserted properly?
- Q. The characters "MIN", "MAX", or "△" are displayed on LCD.
A. Cycle power, or clear characters with a long press to the [HOLD] Button.

SPECIFICATIONS

- Resolution : 0.01mm
- Instrument Error : $\pm 0.03\text{mm}$
- Measurement Range : $-13 \sim 16\text{mm}$
- Display : 4-Digit LCD
- Operating Temperature Range : $0^{\circ}\text{C} \sim 40^{\circ}\text{C}$
- Storage Temperature Range : $-10^{\circ}\text{C} \sim 60^{\circ}\text{C}$
- Auto Power Off : Approx. 20 min.
- Power : Silver Oxide Battery, SR44, 1.55V
- Battery Life : Approx. 1 year with normal usage
- Accessories : Silver Oxide Battery, SR44, 1.55V (for test)

SK Niigata seiki Co., Ltd.

6-15-22, Tsukanome, Sanjo, Niigata, Japan, 955-0055
Tel. : +81-256-31-5660 Fax. : +81-256-39-7730
MAIL: intl.sales@niigataseiki.co.jp
URL http://www.niigataseiki.co.jp